

PLUMLAND AND GILCRUX COMMUNITY TRAVEL PLAN - PRIORITIES

KEY		Walking	Cycling	Public T	Car/Safety	Other (n/a)	Funded	Transfer to other budget
Local Priority in brackets means Local Priority of a scheme assessed for APM funding				Recommended for funding	Linked Request	Duplicate Request		

No	Location	Request	Objectives addressed	Comments	Local Priority	LTP Score	Budget Cost	Overall Priority
9	B5301	B5301 Moota to Parsonby - Road markings and rumble strips near Plumbland		See No. 10	2 (1)	10	£12k	
10	B5301	Warning signs at bends on B5301		See No. 9	6			
11	Gilcrux - General	Roads in and around Gilcrux are unsuitable for cyclists		See 12, 17 + 19	10 (2)	12	£12k	
12	Gilcrux	Signs to alert speeding traffic of children playing		See 11, 17 + 19	4			
19	Gilcrux	'Slow' written on road at each entrance to Gilcrux		See 11, 12 + 17	7			
17	Gilcrux	Signing in Gilcrux for width restriction on road leading to Prospect		See 11, 12 + 9	9			
1	Ellenbank	Problems when 2 HGV's meet at Ellenbank		No feasible solution that wouldn't affect local economy or prohibitive cost	5	-	-	-

14	Bulgill	Re-open the Bulgill train station			-	-	-	Public T
15	General	Increase the number of buses that service the area			8	-	-	Public T
20	Gilcrux	Provide train service from Aspatria through Gilcrux & Cockermouth			-	-	-	Public T

4	Arkleby Bridge	Priority system at Arkleby Bridge		See Aspatria CTP	1		£100k	PTIS
6	Plumbland & Threapland	Footpath for school children between Threapland & Plumbland			3	13	£60k	PTIS

2	Arkleby Bridge	Flooding problem at Arkleby bridge		Maintenance	-	-	-	Maint
3	Calf Lonning	Calf Lonning in poor condition		Maintenance	-	-	-	Maint
5	Plumbland & Threapland	Poor road surface through Plumbland & Threapland		Maintenance	-	-	-	Maint
7	Plumbland	Water off fields floods the road to the school		Maintenance	-	-	-	Maint
8	Ellenhall	Flooding problems at Ellenhall		2 requests - Maintenance	-	-	-	Maint
13	Bulgill	Flooding problems on Bulgill Brow		Maintenance	-	-	-	Maint
16	Gilcrux	Serious flooding on the corner at Gilcrux		Maintenance	-	-	-	Maint
18	66353	Provide map of all drains in Gilcrux Parish with a maintenance schedule		Maintenance	-	-	-	Maint
21	Gilcrux & Greengill	Renovate cast iron signs at Gilcrux & Greengill		Maintenance	-	-	-	Maint
22	Gilcrux	Drainage running down Tallentire Hill onto footways		Maintenance	-	-	-	Maint